

# Fortifone FON-370i 48.80.198.4 Release Notes



Fortifone FON-370i Release June 06, 2016

Copyright© 2016 Fortinet, Inc. All rights reserved. Fortinet®, FortiGate®, and FortiGuard®, are registered trademarks of Fortinet, Inc., and other Fortinet names herein may also be trademarks of Fortinet. All other product or company names may be trademarks of their respective owners. Performance metrics contained herein were attained in internal lab tests under ideal conditions, and performance may vary. Network variables, different network environments and other conditions may affect performance results. Nothing herein represents any binding commitment by Fortinet, and Fortinet disclaims all warranties, whether express or implied, except to the extent Fortinet enters a binding written contract, signed by Fortinet's General Counsel, with a purchaser that expressly warrants that the identified product will perform according to the performance in the same ideal conditions as in Fortinet's internal lab tests. Fortinet disclaims in full any guarantees. Fortinet reserves the right to change, modify, transfer, or otherwise revise this publication without notice, and the most current version of the publication shall be applicable.

FortiVoice Technical Documentation Knowledge Base Customer Service & Support Training Services FortiGuard Document Feedback fortivoice.com docs.fortinet.com kb.fortinet.com support.fortinet.com training.fortinet.com fortiguard.com techdocs@fortinet.com

### **Table of Contents**

4
4
5
5
5
5
6

## Introduction

This document provides a summary of new features, support information and upgrade instructions for Fortifone FON-370i firmware 48.80.198.4 and resolution of known issues in this release.

## **Supported Models**

The 48.80.198.4 firmware supports only the FON-370i.

# **Release Notes**

### **New Features**

None

#### Enhancements

None

## **Upgrade Information**

#### Upgrading to 48.80.198.4 release

FortiVoice supports updating of FON-370i running 48.80.198.4 or earlier releases.

## Issues

The resolved issues include:

- Resolved issue where intercom would take precedence over a call already in place.
- When set externally the phones would not display the correct light sequence for DND, On Hold, Queue, On Call.